



WARNING!

ROTATING SHAFTS MARKED ARE NOT SHIELDED. ANY SHAFT AND COUPLING NOT GUARDED BY LOCATION MUST BE SHIELDED BY AN INTERACTIVE GUARDING SYSTEM. BONDIOLI & PAVESI DECLINES RESPONSIBILITY IF PROPER GUARDS ARE NOT PROVIDED AND MAINTAINED.



| | | | |
|----------------------------------|---------------------------------------------------------------------------------------------------------------------|--------------------------------------|----------------------|
| A | Sostituiti anelli di tenuta, erano 355010035. Aggiunta 'R' ai codici ricambio e codice kit semigusci sul sezionato. | 20/01/2015 | Pini |
| Rev. | Descrizione / Description | Data / Date | Disegnato / Drawn by |
| MONTAGGIO / GEAR ARRANGEMENTS | | RAPPORTO / RATIO | |
| | | 1:1 | |
| GIRI IN ENTRATA / INPUT SPEED | | TIPO DI MACCHINA / TYPE OF IMPLEMENT | |
| 540 | | 1020 | |
| POTENZA IN ENTRATA / INPUT POWER | | PESO / WEIGHT (Kp) | |
| 18 CV - 13 KW | | 6 | |
| RIF. CLIENTE / CUSTOMER REF. | | DISEGNATO / DESIGNED BY | |
| | | Pini | |
| | | DATA / DATE | |
| | | 17-07-2012 | |
| CODICE / CODE | | | REV. |
| S1020100F101 | | | A |

